

**Permit Details Report**

**Report Date:** 12/15/2021 10:16:51 PM

Application Number: 202005267727  
 Form Number: 8

Address(es): 0132 / 048 / 01 SAN ANTONIO PL

Description: A ROCK FALL SLOPE NETTING SYSTEM WITH ROCK ANCHORS INSTALLED ALONG THE TOP, MIDDLE AND BOTTOM EDGES WITH 3MM COMPOSITE CABLED WIRE MESH. TO COMPLY WITH NOV2020022932

Cost: \$100,000.00  
 Occupancy Code: R-2  
 Building Use: 24 - APARTMENTS

**Disposition / Stage:**

Action Date	Stage	Comments
5/26/2020	TRIAGE	
5/26/2020	FILING	
5/26/2020	FILED	
8/6/2020	APPROVED	
8/6/2020	ISSUED	
3/4/2021	COMPLETE	5802513 Final Inspection/Approved

**Contact Details:**

**Contractor Details:**

License Number: 268082  
 Name: ROBERT MAHONY  
 Company Name: SOIL ENGINEERING CONSTRUCTION  
 Address: 927 ARGUELLO ST \* REDWOOD CITY CA 94063  
 Phone: 6503679595

**Addenda Details:**

**Description:**

Step	Station	Arrive	Start	In Hold	Out Hold	Finish	Checked By	Hold Description
1	CPB	5/26/20	5/26/20	5/26/20	8/6/20	8/6/20	VICTORIO CHRISTOPHER	6/29/2020 - Going with paper plans(mr) ELECTRONICALLY SUBMITTED
2	BID-INSP	5/26/20	5/26/20	5/26/20	5/26/20	5/26/20	GREENE MATT	ok to process
3	CP-ZOC	7/8/20	7/8/20			7/8/20	OROPEZA EDGAR	N/A - in this case - netting no taller than 3'-0' feet above grade - sitting flush against rocks to catch or prevent falling debris. No Planning Review per this application.
4	BLDG	8/3/20	8/3/20			8/3/20	PANG DAVID	7/13/20 HOLD by DP: 1) Submit 2nd hard-copy of 6 May 2020 & 6 November 2020 geotechnical reports, and submit PDF of reports on CD-ROM media, as required by the State, 2) integrate DBI special inspection form into dwgs (rock scaling requires geotechnical observation), and 3) Complete Slope and Seismic Zone Protection Checklist and integrate into dwgs. Is this project in a landslide zone?
5	SFFD	8/4/20	8/4/20			8/4/20	MCCORMACK MARCELLA	approved, no inspection required for fire
6	DPW-BSM	8/4/20	8/4/20			8/4/20	CHOY CLINTON	Approved. 8/4/20: No alteration to reconstruct to or reconstruction of City Right-of-Way under this permit. -CC
7	PERMIT-CTR	7/17/20	7/17/20	7/17/20	7/22/20	7/22/20	BOJORQUEZ GUSTAVO	COMMENTS ISSUED BY PLAN REVIEW STATIONS. PROJECT AGENT MUST PICK-UP PLANS TO ADDRESS COMMENTS. PICK-UP HOURS ARE 10 AM - 3 PM M-F. - 7/17/2020 RCVD RESUBMISSION / FWRD TO INTAKE - 07/22/20
8	CPB	8/6/20	8/6/20			8/6/20	SHAWL HAREGGEWAIN	

This permit has been issued. For information pertaining to this permit, please call 628-652-3450.

**Appointments:**

Appointment Date	Appointment AM/PM	Appointment Code	Appointment Type	Description	Tim Slot
3/4/2021	AM	VS	IVR Scheduled	FINAL INSPECT/APPRVD	1
1/22/2021	AM	VS	IVR Scheduled	FINAL INSPECT/APPRVD	1

**Inspections:**

Activity Date	Inspector	Inspection Description	Inspection Status
3/4/2021	Robert Power	FINAL INSPECT/APPRVD	FINAL INSPECT/APPRVD
1/22/2021	Carl Weaver	FINAL INSPECT/APPRVD	OTHER

**Special Inspections:**

Addenda No.	Completed Date	Inspected By	Inspection Code	Description	Remarks
0	1/7/2021	VZENG	13	SPECIAL GRADING, EXCAVATION AND FILLING (GEO. ENGINEERED)	anchor drilling & rock scaling
0	1/7/2021	VZENG	23	OTHERS:AS RECOMMENDED BY PROFESSIONAL OF RECORD	rock anchor & rockfall netting installation & load test rock anchor
0	12/31/2020	MGREENE	1	CONCRETE (PLACEMENT & SAMPLING)	4000 psi 12/31/2020 See engineer's letter dated 12/20/2020. MG

For information, or to schedule an inspection, call 628-652-3400 between 8:30 am and 3:00 pm.

[Station Code Descriptions and Phone Numbers](#)

[Online Permit and Complaint Tracking](#) home page.

**Technical Support for Online Services**

If you need help or have a question about this service, please visit our FAQ area.